




ALTERNADORES SEGUNDA MANO - 3730022600#202 - ALTERNADOR (14V 80A) HYUNDAI ACCENT II (LC) 1.3 (2000-2005)

(Z001)







U.C. REG. BUILT IN

~~MANDO~~ AB180128



37300-22600

13.5V 30A

MANDO MACHINERY CORP. KOREA